ML

App. F 1X-4

1927.

(Miscl)

File No. 32-27

Serial Nos. 8,234

30

Previous References

ML 32-27 Blo 152
ML 21-24 Blo 20+32
Later References 24 Blo 697
GC 21-23 Blo 54, 56+67
Label References
ML 32-27 Blo 61+63

General and Revenue Secretariat.

Serial Nos. Three

Part B for Dec 27

SUBJECT

Revised estimate for repairing the Fort Lamport Walls

Ref L 3358 Dy 8-12-27 the EE Engr requests that in future the above shall be in charge of Public Bldgs Dept in View that the Fort generally & the Engr in Charge of the above

3/1/28.

General and Revenue Secretariat. File No 32 of 192

Serial No. 16

1927

Mulla Mir Khan 3rd City

Letter No 461 J 22nd Oct 1927 from the Chairman City Imp Trust Board forwarding for sanction a revised estimate for Rs 1095/- for repairing the Fort Rampart wall

The present estimate is for Rs 1095/-

It is reported that the total expenditure on this work Comes to Rs 2392/- of which Rs 1297/- has already been paid to the Palace Maramat Dept ~~out of the~~ and the excess of Rs 392/- would be met out of general savings in Town Works

The Chairman also requests for the Cancellation of the ~~Sanction~~ Sanction of Rs 380/- sanctioned on 21st Jan 1927

Draft sanctioning the estimate is submitted for orders

OFFICE OF THE THIRD MEMBER OF COUNCIL 5 NOV 1927 No 16224

CHIEF SEC. 3 NOV 1927 Noted—Counter sheet

Orders 31/10

(This has become a necessary charge of expenditure) 4/11

Ch Secy

7 Sd Hamilton

4/11

WD 6324—SPB—50,000—24-8-27

Dewan

General and Revenue Secretariat. | File No. of 192

Serial No.

DEWAN'S OFFICE
Received on
2. NOV. 1927
Reg No. 3099

1 Draft appd.

2 It is not clear to the Govt. these recurring items of expenditure should be charged to the Improvement Trust. Such expenditure ought to be borne by the Muni or other authority in whom the Property vests.

CSB
9/11

Pleas submit A
& Dewan after
return.

9/11

10/11

3. Secretary may speak
Dewan's return—

10/11

10/11

L 2659-60 & 11/2/27
Rs Chairman To Rs Bijapur
Re Completion
Sanctions the revised estimate
for Rs 1095/- for repairing the
Fort Ramparts work as Proposed

Submitted with reference to para

24/11

Dewan

DEWAN'S OFFICE
Received on
24 NOV. 1927
Reg No. 3196

NOTE—Contn. sheet

1927

General and Revenue Secretariat. File No. 32 of 1927

Serial No.	
	Strictly speaking I am the P.W.D. that ought to look after the Port work, as they do the Galiwara. The C.E. may be asked to do them in future & the Y.B. advanced of the responsible
	MJ 25-11-27
	Draft letter to the Chief Engineer submitted Ch. Sec'y 25/11 C. Manuscript the draft is for approval
	Typed draft for approval Ch. Sec'y
	Ch. Sec'y)
30	L3358 of 8/12/27 to Chief Engineer directing them to look after the works in future. Copy to the Comptroller, Medical & the Pharmacist and Ry. Branch

CHIEF SECRETARY'S 5 DEC. 1927

B

Note—Contn. sheet

No. 461 Estimate. Report &c.

OFFICE OF THE CHAIRMAN,
CITY IMPROVEMENT TRUST BOARD, MYSORE,
Dated 20th October 1927.

1923
8 OCT 1927

FROM

C S KUPPUSWAMAIENGAR, Esq.,
Chairman, City Improvement Trust Board,
Mysore.

To

The Chief Secretary.
to the Government of His Highness the
Maharaja of Mysore

— W 32-27-16

Sir,

I have the honour to forward herewith a revised estimate for Rs 1,095/- for repairing the Port Rampart Wall, sanctioned by the Board of Trustees by Circulation during September 1927, and to request that you may be so good as to obtain the sanction of Government thereto

2 The report accompanying the estimate, in duplicate, explains the nature of the work and necessity for revising the estimate.

3 A sum of Rs 2,000/- is provided for this work in the current year's budget Taking the amount of Rs 1,297/- already paid to the Palace Marmath Department in the early part of August, being the arrears due to the Department for repairing the Port Rampart wall during the years 1923-to 1926, the total expenditure on the work comes to Rs 2,392 resulting in an excess of Rs 392/- over the budget provision This excess may be met out of general savings in other works With a view to complete the work before the Dasara Festivities, the work was put in hand, in anticipation of sanction The original estimate for Rs 380 sanctioned by Government in their order No L 449-Se dated 21st July 1927 may kindly be got cancelled

after according sanction to the revised estimate

I have the honour to be

Sir

Your most obedient servant

Chairman

No 270/Misc one file

Office of the Chairman
City Improvement Trust Board Mysore

8th September 1927

Memorandum

The accompanying revised estimate for Rs 1 095/- for repairing the Fort Rampart wall is circulated among the Trustees for sanction The work is of an urgent nature

Sd C S. Kuppuswamiengar
Chairman

Trustees

1 Sir Charles Todhunter K C S I

2 B Mahomed Usman Esquire L M S

3 The Health Officer, City Municipal Council Mysore

Sanctioned (Id) 9/9

4 J E A D'Cruz Esq A C E B C E

5 Rajakaryaprasakta D K Darsha, Esq B A Approved (Id) D K R. 9 9 27

6 Mahomed Sait Esq Approved MA(Id) 10 9 27

7 Tippu Sultan Alikhan Esquire Approved (Id) A K

8 K Dhanakotichetty Esquire Approved (Id) K D Chetty 9 9 27

"Copy"

Chairman

Report to accompany the revised estimate for repairing the Fort Rampart Wall

Amount of estimate Rs 1,095/-.

—

Reference:- D O letter No 122 dated 22nd August 1927 from the Huzur Secretary to His Highness the Maharaja.

An estimate amounting to Rs 380/- for white and colour washing the parapet wall above the Rampart wall in Fort, was sanctioned by the Board of Trustees in their Resolution No III dated 18th June 1927 During execution of the work, it was desired that necessary repairs for the parapet and Rampart walls might also be done simultaneously As the original estimate was only for white and colour washing the parapet wall and as the work had to be completed before the Birthday Festivities, repair work had to be put off

After a careful examination of the parapet and rampart walls and the western entrance, it is found that the walls are pitted throughout requiring good lot of repairs Necessary provision for repairs is made in the estimate The total cost of the proposal comes to Rs 1 095/-

A sum of Rs 2 000/- is provided for this work in the current year's budget Taking the amount of Rs 1,297/- already paid to the Palace Maramath Department in the early part of August, being the arrears due to the Department for repairing the Fort Rampart wall during the years 1923 to 1926, the total expenditure on the work comes to Rs 1,095 plus 1,297=Rs 2,392/- resulting in an excess of Rs 392/- over the budget provision This excess may be met out of general savings in other works.

As the work is to be completed before the ensuing Dasara Festivities, early sanction to the estimate is requested. The original estimate may be cancelled after according sanction to this estimate

Mypone Valley Improvement Trust Board
Revised estimate for repairing ~~above~~ the ~~fort~~

Rampart wall Mypone—

Details of work	No	Dimensions	Quantity	Rate	Cost
Whit and colour washing two coats including scraping around the Parapet wall of Rampart. (As per inventory)					
In front of the Main Gate each way big	2	22 3/4	34 1/2	1661	
—do— —do— small	2	23 3/4	38	1815	
—do— Mandapam with female	2	9	6	432	
—do— Veranam on the centre	2	10	5	100	
—do— Sides	2	7	5	70	
—do— Corners of sides	2x2	8 1/2	2	68	
—do— Sides of small arch way	2	6 1/2	3	39	
—do— Elephant at sides & pilaster	2	6 1/4	9	112	
From South west gate go to N.-west	1	253	14	3682	
—do—	1	499	13 1/2	6736	
—do—	1	229	12	2748	
North-west below gate way both sides	2	24	37	1776	
—do— at sides	4	13	34	1768	
From western gate go to N.-ornamental	1	84	12	1008	
—do—	1	360	8	2880	
—do— North up to Fort North gate	1	769	9	6921	
From Fort North gate go N.-E	1	1442	13	18754	
—do—	1	194	17	3298	
—do—	1	264	12	3168	
—do— up to Coal way	1	183	13	2379	
From Custom gate way go south and Custom side	1	9	5	45	
	1	112	14	1568	
up to the demantled portion	1	282	14 1/2	3509	
—do—	1	896	15	13440	
up to the South gate	1	215	13	2795	
From South gate go South west	1	97	7 3/4	752	
up to South west gate	1	735	13	9555	
Eastern side Legal	1	16	16 1/2	264	
Total in Sft				90458	
do in Sq				905	

Sqr. 8 453

Brought forward					
Chunam Concrete including removing the old concrete and cart away					
or Burnd Earth in marks wherever necessary					
from western gate in front of Mail Office	1	5 1/4	4 10/16	1/2	7
up to Western police gate	1	2 3/4	3 1/4	1/4	2
— do —	1	8	3/4	1/4	2
— do —	1	1 1/2	1	1/2	1
— do —	2	100	1/2	1/4	25
— do —	1	6	2 1/2	1/4	4
— do —	1	97	1/4	1/4	6
— do —	1	2	1	1/4	1
— do —	2	4	1	1/4	2
— do —	1	45	1 1/2	1/4	17
— do —	2	2	1	1/4	1
— do —	1	1 1/2	1/2	1/4	1
— do —	1	4	3/4	1/4	1
from western gate go to South gate	1	9	2 1/2	1/4	6
— do —	1	6	2	1/4	3
— do —	1	5	1 3/4	1/4	2
— do —	1	10	4	1/4	10
— do —	1	2	1 1/2	1/4	1
— do —	1	2 1/2	1 1/4	1/4	1
— do —	1	3	4	1/4	3
from North gate go North East	1	9	2 1/2	1/4	6
— do —	1	6	3	1/4	5
— do —	1	4	1/2	1/4	1
Total					148 ft
Chunam plastering including removing old plastering					
from western gate in front of new Mint					
up to the police west gate corner	9	1	1/2		4
near gate North-west	1	6 1/4	3 1/2		22
— do —	1	12 1/2	1		12
North West	1	2	3 1/2		7
Carried over					

Brought forward				
North west end	1	4½	1	5
- do -	1	3	½	2
- do -	1	28½	1	14
- do -	1	8½	2½	9
- do -	1	6	4	24
- do -	1	5½	1	6
- do -	1	16	½	8
- do -	1	7	¾	7
- do -	1	5	½	2
- do -	1	12	½	6
- do -	1	4½	3½	25
- do -	1	95	6	570
- do -	1	95	4½	427
	1	33½	6	201
- do - Inside ft wall	1	33	4	132
Gap	1	5	5	25
- do - side	1	6½	3½	18
- do -	1	3½	3½	9
Inside	1	10	4	66
Top	1	33½	5½	157
Gap	1	5	4½	23
- do -	1	4½	2	5
Inside	1	33	4	128
Top	1	33	5	165
Inside	1	15	¾	11
Top	1	30	5	150
Gap	1	6	½	3
Top	1	26	4½	124
Gap	1	4½	4½	22
Inside wall	1	3	1½	4
- do -	1	10	2	20
- do -	1	5	4	20
- do -	1	10	1½	15

Carried over

Brought forward					
Top	1	30	2		150
Gap side	1	3	2		6
Top	1	31	4¾		147
-do-	1	5	1		5
Top	1	71	5		355
out side	1	71		3¾	266
Inside	1	6	4		24
Out side wood	1	60	3½		123
- Top -	1	5	¾		4
Top and front out-side	1	95	2		190
-do-	1	24	2		48
Front outside	1	5	½		3
Top	1	21	2		42
Gap	1	20	4½		90
~~Front outside~~ Gap	1	2	1		2
Front out-side	1	18	4		72
Top	1	21	4½		90
Gap	1	2	1		2
Front out side	1	18	4		72
Top	1	23	½		12
-do-	1	22	½		11
Front	1	26	3¾		98
Top	1	12	½		6
-do-	1	5	½		2
- do -	1	2	1		2
To	1	47	¾		35
Front edge	1	10	¾		8
Below western gable top side	2	13	3		78
- do -	1	22		1	22
do -	2	5	3		30
From western gable of below to north	2	4	2		16
Ornamental Parapet	1	5	½		2
-do-	1	3	2		6
-do-	2	2	2		8
- do -	1	1½	½		2
- do -	1	4	½		2

Carried over

Brought forward

Ornamental parapet wall	1	50	¾		38
- do -	1	7	1		7
- do -	1	8	5		40
- do -	1	4	4		16
- do -	1	5	1		5
- do -	1	12	2		24
- do -	1	7	2		14
Setoff on the ornamental Parapet	3	8	½		12
- do -	3	8	½		12
Ornamental parapet bottom	1	21	½		10
do	1	15	1½		23
- do - top	2	2	2		8
- do -	1	15	1½		22
- do -	1	50	1½		75
- do -	5	14	1		70
- do -	2	3	2½		15
up to the North gate	1	250	2		500
South wall up to south gate	1	12	½		6
- do -	1	10	½		5
- do -	1	2	¾		2
- do -	1	1½	2		3
do	1	3	3		9
- do	1	3	1½		5
- do	1	7	⅝		4
- do	1	4	½		2
from North gate to North East	1	4	½		2
- do	1	30	½		15
- do	1	10	½		5
- do	1	10	½		5
- do	2	4	3		12
- do -	1	4	5½		10
- do -	1	7½	3½		26
- do -	1	5	2½		12
do	1	20	1		20
- do -	1	15	2		30
- do -	1	10	1½		15
- do -	1	15	2		30
Eastern wall	1	24	7½		180
- do -	1	8	1		8
- do -	1	7	¾		5
Inside	1	75	¾		56

Carried over

Brought forward								
Inside	1	9	2½	23				
-Do-	1	4	3	18				
-Do-	1	4	½	2				
-Do- South west	1	9	2½	22				
-Do-	1	6	2	12				
-Do-	1	3	1¾	9				
-Do-	1	10	4	40				
-Do-	1	2	1½	3				
-Do-	1	2½	1½	3				
-Do-	1	3	4	12				
Total in Sft				606.				
-Do- Sqrs				61	Sqrs	4		244
Repairing the oblong course around the foot ball with brick in mortar & plastering complete	1	75		75	Rft	8		3
Repairing the ornamental flower work with bon elephant figures complete								
Western gate in front of Mch. office	8			8	Nos	8		4
Pointing with Chunnam mortar around the Ramped walk outside including packing with chungy or chips & Scaffolding charges Complete								
For the Sorge above work around				30	Sqrs	4		2
Ideem washing to the newly repaired portion Half the Rate				30	Sqrs	0	8	0
Total Rupees								10
Contingencies & other unforeseen charges at 5%								
Grand Total Rupees								13

Chief Board Engineer
19/7/19

Chairman

Ypres City Improvement

— Trust Board —

— "Original" —

Revised Estimate for repairing Post Rampart Wall around Ypres

---

Amount of Estimate Expire 1095

Report to accompany the revised estimate for repairing the Fort Rampart Wall

Amount of estimate Rs 1,095/-

—

Reference - D O letter No 122 dated 22nd August 1927 from the Huzur Secretary to His Highness the Maharaja

An estimate amounting to Rs 380/- for white and colour washing the parapet wall above the Rampart wall in Fort, was sanctioned by the Board of Trustees in their Resolution No III dated 16th June 1927 During execution of the work, it was desired that necessary repairs for the parapet and Rampart walls might also be done simultaneously As the original estimate was only for white and colour washing the parapet wall and as the work had to be completed before the Birthday Festivities, repair work had to be put off

After a careful examination of the parapet and rampart walls and the western entrance, it is found that the walls are pitted throughout requiring good lot of repairs Necessary provision for repairs is made in the estimate The total cost of the proposal comes to Rs 1,095/-

A sum of Rs 2,000/- is provided for this work in the current year's budget Taking the amount of Rs 1,297/- already paid to the Palace Maramath Department in the early part of August, being the arrears due to the Department for repairing the Fort Rampart wall during the years 1923 to 1926, the total expendi-ture on the work comes to Rs 1,095 plus 1,297=Rs 2,392/- resulting in an excess of Rs 392/- over the budget provision This excess may be met out of general savings in other works.

As the work is to be completed before the ensuing Dasara Festivities, early sanction to the estimate is requested The original estimate may be cancelled after according sanction to this estimate

Chairman

—

G.R.S VI G 34]

SUBJECT .....

Diary No. of letter replied to.....

General and Revenue Secretariat

( )

, the 192

Date of issue 15-11-27

Signed by Asst. to C. M. Engineer

May this be

i Printed ?

ii treated as a standing order ?

iii published in the Gazette, English Part ?

iv translated ?

v placed at the disposal of the press ?

vi published in the Gazette, Kannada Part ?

Section Mil

File No 32 - 27

Serial No. 23

Proceedings of the Government of His Highness the Maharaja of Mysore

Read— g o no L449-50 of wh 32-27-2 dt 21st July 1927 sanctioning among other works, an estimate for Rs 300/- for repairing the Fort Rampart wall in the mysore city

2) Letter no 461 dt 22nd oct 1927 from the Chairman City Imp Tr Bd Mysore recommending, Sanction to a revised estimate for Rs 1095/- for repairing the Fort Rampart wall and stating that the total expenditure on the works comes to Rs 2392/- (including the amount of Rs 1297/- already

Order Thereon—No.

paid to the Palace
Paramath Dept in
the early part of August 1927
being the arrears due
to the dept for repairing
the Fort Rampart wall
during the years 1923 to 1926) that the
which results in an
excess of Rs 392/- over
the budget provision
and proposing to meet
this excess out of the
General Savings in other
works and requesting
Cancellation to the
Original estimate of Rs
Rs 380/- sanctioned in the G.O
read as para (1)

order no 1265 Fin
~~Sanctions~~ the revised
estimate and the original
estimate ~~of~~ Cancelled

List of enclosures

Mw 3/11 Chief Engg to Govt

To the Chairman To PD Board Wm Estimate
the Comptroller

Copied by

Examined by

VD 2B—GPB—1,000,000—21-1-28

Proceedings of the Government of His Highness
the Maharaja of Mysore.

Read :-

Government Order No.L.449-50/ Ml.32-27-2 dated 21st July 1927 sanctioning among other works an estimate for - Rs.380/- for repairing the Fort Rampart wall in the Mysore City.

2. Letter No.461 dated 22nd October 1927 from the Chairman City Improvement Trust Board,Mysore recommending sanction to a revised estimate for Rs 1095/- for repairing the Fort Rampart wall and stating that the total expenditure on the works comes to Rs.2,392/- (including the amount of Rs 1,297/- already paid to the Palace maramath Department in the early part of August 1927 being the arrears due to the Department for repairing the Fort Rampart wall during the years 1923 to 1926) that this results in an excess of Rs 392/- over the budget provision and proposing to meet this excess out of the General Savings in other works and requesting cancellation to the original estimate of Rs 380/- sanctioned in the Government Order read in para (1).

Order No.L. 2659-60/Ml.32-27-23
Dated,Bangalore, the 15th November 1927.

The revised estimate is sanctioned and the original estimate cancelled.

M Venkatasubbiyer
For Chief Secretary to Govt.

To
The Chairman,City Improvement Trust Board,Mysore
The Comptroller,Mysore Government.

MK.S
27/11.

L3358/W-32-27-38

8/12-27

To

The Chief Engineer of Mysore
Bangalore

Sir,

I am directed to state that ~~it is~~ ~~Government~~ the Fort Rampart wall in ~~the~~ Mysore City, which is ~~being~~ now looked after by the Mysore City Improvement Trust Board ~~and the expenditure in this connection met from the Trust Board Funds.~~ It is stated in view of the fact that Fort Gateways in the ~~Mysore~~ City are under the charge of the Public Works Department, ~~Government direct that the Fort Rampart wall~~ be also ~~be taken~~ looked after by the ~~Public Works~~ Department ~~and~~ requesting that they may be some Department in future and the Trust Board ~~be~~ relieved of the responsibility

I have etc.,

DRAFT) Chief Secry to Govt

No L3359-61

Copy to Chairman, City Improvement Trust Board, Huzur Secretary to His Highness the Maharaja of Mysore, and the Comptroller to Government, for information.

By Order,

DRAFT)

For Chief Secry to Govt

Ck
3/12

5/12-27